

**NEW YORK STATE DEPARTMENT OF STATE**

Division of Code Enforcement and Administration

41 State Street Albany, New York 12231

Phone no. (518) 474-4073 [Fax] (518) 486-4487

Facsimile Transmission Sheet

DATE: September 1, 2005

TO: ~~Dave Abrcy~~ Mike Dewine

FAX: 664-5672

FROM: Cheryl A. Fischer, P.E.
Assistant Director for Code Interpretation

NOTE: Cathedral Ceiling

This is in response to your question whether the application of spray in foam in the rafter space of a cathedral ceiling, even a flat ceiling, requires ventilation of the space in accordance with *Residential Code of New York State (RCNYS)* section R806.1. NO. Any such impervious material which completely fills the rafter space is permitted without ventilating the roof.

Number of sheets (including cover sheet) 1

If there is a problem or question, call (518) 474-4073

****Please Note:** This fax and any of its contents may contain Department of State privileged or confidential information. This fax is intended solely for the use of the individual or entity to which it is addressed. If you are not the intended recipient of this fax, you are hereby notified that any dissemination, distribution, copying, or action taken in relation to the contents of and attachments to this fax are strictly prohibited, and may be unlawful. If you have received this fax in error, notify the sender immediately, and permanently destroy the original, and any copy of this fax.